

**875—90.7 (89) Fees.**

**90.7(1) *Special inspector certification fee.*** A \$40 fee shall be paid annually to the commissioner to obtain a special inspector certification pursuant to Iowa Code section 89.7, subsection 1.

**90.7(2) *Certificate fee.*** A \$25 fee shall be paid for each one-year certificate, a \$50 fee shall be paid for each two-year certificate, and a \$100 fee shall be paid for each four-year certificate.

**90.7(3) *Fees for inspection.*** An inspection fee for each object inspected by a division inspector shall be paid by the appropriate party as follows:

- a. A \$40 fee for each water heater supply boiler.
- b. An \$80 fee for each boiler, other than a water heater supply boiler, having a working pressure up to and including 450 pounds per square inch or generating between 20,000 and 100,000 pounds of steam per hour.
- c. A \$200 fee for each boiler, other than a water heater supply boiler, having a working pressure in excess of 450 pounds per square inch and generating in excess of 100,000 pounds of steam per hour.
- d. A \$40 fee for each pressure vessel, such as steam stills, tanks, jacket kettles, sterilizers and all other reservoirs having a working pressure of 15 pounds or more per square inch.
- e. In addition to the applicable object's inspection fee, if the division cannot follow normal practice of scheduling inspections in a cost-effective manner due to a request by an owner or user for a customized schedule, travel expenses may be charged at the discretion of the division.
- f. Inspections and code qualification surveys made by the commissioner at the request of a boiler or tank manufacturer shall be charged at a rate set by the commissioner not to exceed the rate currently charged by the various insurance companies for performing a similar service. This charge shall not void the regular fee for inspection or certification when the boiler or tank is installed.
- g. If a boiler or pressure vessel has to be reinspected through no fault of the division, there shall be another inspection fee as specified above. However, there shall be no fee charged for the first scheduled reinspection to verify that ordered repairs have been made.

**90.7(4) *Fees for attempted inspections.*** A \$20 fee shall be charged for each attempt by a division inspector to conduct an inspection which is not completed through no fault of the division.